



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program February 3, 2010

Reviewed: 

Mine Name: Expectation	Permit Number: S/035/0024
Operator Name: Mark Miller	Inspection Date: October 27, 2009
Inspector(s): L Heppler	Time: 11:00 am
Other Participants: none	Mine Status: Suspended

Elements of Inspection	Evaluated	Comment	Enforcemen
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>


Bond Renewal Date: 04-06-2006 **Bond Amount:** \$3,000 **Permit fee** is delinquent from 2006 to 2010, the total due is \$600

Purpose of Inspection: Routine annual Inspection. This site was inspected as a small mine site on 10/16/2008

Inspection Summary: The trackhoes need to be removed from the site along with the tracks and any trash. Both trackhoes are un-operable, one has had the motor removed the other no longer has the tracks. To remove the trackhoes the Division would incur considerable costs, as they were abandoned off road. A road would need to be built suitable for a crane to load them on a lowboy. The area will need to be regraded and seeded.

Photos were taken to document site conditions.

Conclusions and Recommendations: The equipment must be removed and all delinquent fees paid. DOGM will continue to monitor this site until these issues are resolved. This site has been turned over to the Attorney Generals office for resolution. Operator has 30 days to comply with all local, state and federal rules.


Inspector's Signature 

LAH:vs

cc: Mark Miller

O:\M035-SaltLake\S0350024-Expectation\inspections\Insp-02062010.doc





Abandoned Trackhoes